# COMPLETION REPORT

| | | |
|---|---|---|
| 1 | Name of the work | Improvements to Bhuvaneshwarinagara 8th Main road upto Maheshwaramma temple in Ward No. 14, Bagalagunte. |
| 2 | Sanctioned Estimate No. & Date | |
| 3 | Head of Account which is chargeable | ₹-2434 |
| 4 | Instrument Order NO. & Date | |
| 5 | Name Of Contractor | KRIDL |
| 6 a | Time Stipulated for Completion of work | |
| b | Delay in Exculpation of Work | |
| 7 | Measurement recorded in | 3414 : Pno 34132 to 34132 |
| 8 | Check Measurement of the Asst | |
| 9 | Name of the office/official in charge of the work | |
| 10 | a) Asst. Eng/junior Eng | ಪಿ.ಎಸ್.ಯಲ್ಲಪ್ಪ |
| | b) Asst. Exe Engineer | ಮಂಜುನಾಥ |

| Sanctioned Estimate Amout | Amout Claims As per Actually Vide As per bills | Excess | Savings |
|---|---|---|---|
| 6.04 | | — | |

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER.

ASSIATANT EXECUTIVE ENGINEER